



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD AUG 19 '14

OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 8-19-14 Operator Emergentes API #30-0 45-24909

Property Name Richardson Well No. 1E Location: Unit Section 2 Township 27 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 104 Intermediate 119 Casing 104 Bradenhead 80

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	15		115		
10 min	0		121		
15 min	0		130		
20 min	0		130		
25 min	0		135		
30 min	0		135		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u> / </u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u> / </u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 119

REMARKS:

Med blow through 1/4" needle valve to very
light with up to full 30 min test.

By Eugene Burbank
Production Foreman
(Position)

Witness Monica Kuehling
Gas analysis

E-mail address