



7-30
3-30

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/20/2014 Operator COPC API #30-0 45-34070

Property Name Ludwick LS Well No. 21F Location: Unit E Section 31 Township 30 Range 10

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 145 Intermediate 52 Casing 149 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	52	153	0	155
10 min	0	52	154	0	155
15 min	0	52	154	0	155
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		RCVD AUG 20 '14
Gas & Water		OIL CONS. DIV.
Water		DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Just a puff on bradenhead. Intermediate blew down
to nothing in 8min 30sec.

By Paul Sikora
MWD Run 311
(Position)

Witness Paul Wiebe

E-mail address _____