NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-15-14 Operator Burlington Res API #30-0 45-27003

Property Name Allison Ut Well No. 108 Location: Unit ___ Section 23 Township 32 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 16 Intermediate N/A Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		9		
10 min	0		9		
15 min	0		9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	
Nothing		
Gas	/	
Gas & Water		
Water		

RCVD JUL 15 '14
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: bad pump downhole. little puff when opened

By Mike Lima

MSO
(Position)

Witness Monica Kuehling

E-mail address _____