

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Day 4	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004523513
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter F	Section 08	Township T29N	Range R08W	Feet from the 1590	North/South Line North	Feet from the 1450	East/West Line West	County: San Juan
------------------	---------------	------------------	---------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.74198 Longitude 107.70121

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 729 MCF	Volume Recovered: none
Source of Release: hung oil dump from separator	Date and Hour of Occurrence: 7-7-14 3pm - 7-10-14 12 pm	Date and Hour of Discovery: 7-10-14 12 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith - NMOCD Shari Ketcham - BLM	
By Whom?: Courtney Cochran - BP	Date and Hour: 7-11-14 9 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

OIL CONS. DIV DIST. 3

If a Watercourse was Impacted, Describe Fully.*

JUL 16 2014



Describe Cause of Problem and Remedial Action Taken.*

Field technician arrived on location to check cause of drop in production. He found the oil dump hung open on the separator to the production tank with the compressor still running. Well is producing currently. Technician adjusted the dump controller and corrected the issue.

Describe Area Affected and Cleanup Action Taken.*

No clean-up action possible. Natural gas dissipated to the atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 9/5/14	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/14/2014 Phone: 505-326-9457		

* Attach Additional Sheets If Necessary

#NCS 142 4853 377

①