



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/11/14 Operator Burlington Resources API #30-0 39-07153
Property Name San Juan 286 CH Well No. 75 Location: Unit Section 3 Township 27 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 83 Intermediate N/A Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>104</u>		
10 min	<u>0</u>		<u>107</u>		
15 min	<u>0</u>		<u>104</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

RCVD SEP 11 '14

OIL CONS. DIV.

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

This well has not connected to prod. casing
Making a lone pipe to intermediate.
Nothing when opened.

By Kevin Miller

Witness

Monica Kuehling

(Position)

E-mail address