



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 9-18-07 Operator Patina San Juan, Inc. API # 3003922100

Property Name HURON 2E Location: Unit M Section 2 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 56 Intermediate - Casing 123 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>123</u>	<u>-</u>				
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute SI							


Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	<u>-</u>
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:



By Greg Vigil - GJV
LEAD PUMPER
(Position)

Witness _____