



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-19-07 Operator Patina San Juan, Inc. API # 3003923505

Property Name JICARILLA 3E Location: Unit F Section 8 Township 26 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 54 Intermediate - Casing 95 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>6</u>	<u>95</u>	<u>-</u>			Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	<u>X</u>
20 minutes						No Flow	<u>-</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 6 Intermediate \_\_\_\_\_

REMARKS:



By

Greg Vigil - [Signature]  
LEAD PUMPER

(Position)

Witness \_\_\_\_\_