



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-19-07 Operator Patina San Juan, Inc. API # 3003906633

Property Name JICARILLA 3 Location: Unit B Section 8 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 63 Intermediate — Casing 67 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor									
5 minutes	<u>0</u>	<u>67</u>	<u>—</u>						<u>X</u>	<u>—</u>				
10 minutes														
15 minutes														
20 minutes														
25 minutes														
30 minutes														
5 minute SI														

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:



By Greg Vigil - [Signature]
LEAD PUMPER
(Position)

Witness _____