



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3dldistrict.htm>

ROVD SEP 22 '14

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/22/2014 Operator EverVest API #30-045-31129
Property Name Southern Union Well No. 1B Location: Unit K Section 19 Township 31 Range 12
Well Status(Shut-In or Producing) Initial PSI: Tubing 121 Intermediate 20 Casing 120 Bradenhead 179

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	20	120	0	120	Steady Flow <u>X</u> <u>X</u>
10 min	0	20	120	0	120	Surges <u>X</u>
15 min	0	20	120	0	120	Down to Nothing
20 min	0	20	120	0	120	Nothing
25 min	0	20	120	0	120	Gas
30 min	0	20	120	0	120	Gas & Water
						Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Quick Puff on bradenhead, down to vapours in ~1 sec, vapor flowed for entire 30 min. Low puff after 5 min shut in. Int. Hard blow for 1 min 15 sec, down to whisper + vapors in 1 min 45 sec. Flowed vapor for entire test. Request gas analysis + well bore schematic.

By Jimmy Schmit
Operator
(Position)

Witness Jonathan D. Kelly

E-mail address _____