



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/3district.htm](http://emrdd.state.nm.us/ocd/District%20III/3district.htm)

RCUD SEP 30 '14

BRADENHEAD TEST REPORT

OIL CONS. DIV.

(submit 1 copy to above address)

DIST. 3

Date of Test 30-SEP-2014 Operator E-NEVEST API #30-0 45-10161

Property Name PAYNE Well No. 2 Location: Unit H Section 35 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 180 Intermediate N/A Casing 190 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			190		
10 min			190		
15 min			190		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT

By Alp Chaudhary

Witness [Signature]

Pumper
(Position)

E-mail address _____