



NEW MEXICO ENERGY, MINERALS and  
NATURAL RESOURCES DEPARTMENT

RCVD OCT 6 '14

OIL CONS. DIV.

DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-6-14 Operator FPOC, LLC API # 30-0 31-21006

Property Name Torreón Wash 36 State Well # 1 Location: Unit I Sec 36 Twn 20 Rge 5

Land Type:

State /  
Federal \_\_\_\_\_  
Private \_\_\_\_\_  
Indian \_\_\_\_\_

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal \_\_\_\_\_  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas /  
Pressure observation \_\_\_\_\_

Temporarily Abandoned Well (Y/N): (N) TA Expires: \_\_\_\_\_

Casing Pres. 0 Tbg. SI Pres. \_\_\_\_\_ Max. Inj. Pres. \_\_\_\_\_  
Bradenhead Pres. 0 Tbg. Inj. Pres. \_\_\_\_\_  
Tubing Pres. 1/A  
Int. Casing Pres. 1/A

Pressured annulus up to 560 psi. for 45 mins. Test passed failed

REMARKS:

Retained 5441  
drilled cement to retainer.

By [Signature]  
(Operator Representative)

Witness [Signature]  
(NMOCD)

(Position)

Revised 02-11-02