



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3distric.htm](http://emnrd.state.nm.us/ocd/District%20III3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/20/14 Operator Enervest API #30-0 45-25910

Property Name Clayton Well No. 2 Location: Unit K Section 2 Township 30N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 88 Intermediate NA Casing 88 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		88		
10 min	0		88		
15 min	0		88		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

RCVD OCT 17 '14
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Slight puff

By Jerry Padilla
Operator
(Position)

Witness _____

E-mail address _____