



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District BU3/district.htm](http://emnr.state.nm.us/ocd/District%20BU3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/26/2014 Operator Enerva-SI API # 30-045-25953

Property Name Payne Well No. 3E Location: Unit 2 Section 26 Township 31N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 70 Intermediate Casing 76 Bradenhead 86

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		90		
10 min	0		90		
15 min	0		90		
20 min	0		90		
25 min	0		90		
30 min	10		90		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>30 min</u>	RCUD OCT 17 '14
Surges	OIL CONS. DIV.
Down to Nothing	DIST. 3
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Csg did not drop pr.

By [Signature]
[Signature]
(Position)

Witness

E-mail address