



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District1W3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/21/14 Operator Enervest API #30-0 45-31129

Property Name Southern Union Well No. 1B Location: Unit K Section 19 Township 31 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing 121 Intermediate 20 Casing 120 Bradenhead 177

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Int	Csg	Int	Csg
5 min	0	20	120	0	120
10 min	0	20	120	0	120
15 min	0	20	120	0	120
20 min	0	20	120	0	120
25 min	0	20	120	0	120
30 min	0	20	120	0	120

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	X
Surges	X	
Down to Nothing		ROVD OCT 17'14
Nothing		OIL CONS. DIV.
Gas		DIST. 3
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Braden has quick surge then just fumes for remaining time
Int. had a flow for about 1:15 with some vapors then, down to
whisper with vapors entire time.

By Jimmy Bohanif
operator
(Position)

Witness Jonathan D. Kelly

E-mail address _____