



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmrds.state.nm.us/ocd/District III3district.htm](http://emmrds.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/25/2014 Operator Eneiverst API #30-0 45-31206

Property Name harm way Rd 30 Well No. 29 Location: Unit 15 Section 30 Township 31N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 200 Intermediate Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>RCVD OCT 17 '14</u>
Surges	<u>OIL CONS. DIV.</u>
Down to Nothing	<u>DIST. 3</u>
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: SI for BHP Bombs.

By Alex chon

Witness

Pumper
(Position)

E-mail address