



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

OIL CONS. DIV DIST. 3

NOV 25 2014

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11/25/2014 Operator Maralex Disposa API #30-045-33464

Property Name Center Point Slup Well No. 1 Location: Unit P Section 24 Township 31 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 1450 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	0	0	0	0
10 min	0	0	0	0	0
15 min	0	0	0	0	0
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing		
Gas		
Gas & Water		
Water	✓	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

Bradenhead started dripping water 1 min into test
Slight blow on intermediate about 5 seconds.

By D. R. New
Eng. Manager
(Position)

Witness Paul Wicks

E-mail address