



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-1-14 Operator Lizard OEG API #30-0 45-24044
Property Name Sangre de Cristo Well No. 25 Location: Unit 34 Township 30 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	11		0		
10 min			0		
15 min	5		0		
20 min	3		0		
25 min	2		0		
30 min	0.8		0		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV DIST. 3

DEC 01 2014

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE N/A

REMARKS:

sp. t black water - then gurgle with gas for next
730 min test.

By Arthur Sullivan
Pumper
(Position)

Witness Moussa Kuehling

E-mail address _____