



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 07 2013

Date of Test 4-23-13 Operator WPX Energy API #30-0 3921703

Property Name Rosa Unit Well No. 064 Location: Unit A Section 29 Township 31N Range 05W

Well Status (Shut-In or Producing) Initial PSI: Tubing 151 Intermediate 77 Casing 169 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	
Down to Nothing	☒
Nothing	☒
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 30

REMARKS:

Bradenhead had 0 psi. Left valve open - Intermediate had 77 psi blew down to nothing. After 5 min shuttin it had 30 psi blew down to nothing again but some white foam started to come out took a sample left valve closed

By Stanley Dean

Witness _____

Sr Tech

(Position)

E-mail address _____