



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

APR 23 2013

Date of Test 4-15-13 Operator Chevron midcont API # 30-039-21975

Property Name Rincon Well No 88A Location: Unit 2 Section 13 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 79 Intermediate X Casing 77 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME	<u>Light</u>				
5 min	<u>Blow</u>		<u>77</u>		
	<u>Light</u>				
10 min	<u>Blow</u>		<u>77</u>		
	<u>Light</u>				
15 min	<u>Blow</u>		<u>79</u>		
	<u>Light</u>				
20 min	<u>Blow</u>		<u>79</u>		
	<u>Light</u>				
25 min	<u>Blow</u>		<u>81</u>		
	<u>Light</u>				
30 min	<u>Blow</u>		<u>82</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>X</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3

INTERMEDIATE X

REMARKS:

Had ^{light} Steady Blow for Full Test

By Randy Culcote

Witness _____

Culder service
(Position)

E-mail address Randy.C@calderservice.com

4-16-13