



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.d.state.nm.us/ocd/District/W3d1stb1c.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 07 2013

Date of Test 6-5-13 Operator Chevron midcont API #30-039-26682

Property Name Rincon Well No. 229m Location: Unit B Section 34 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 141 Intermediate 42 Casing 149 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	42	150	0	151	
10 min	0	42	151	0	151	
15 min	0	42	151	0	151	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	X 10 sec
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1

REMARKS:

gas sample taken off intermediate and csg

By Randy calder

Witness _____

calder service
(Position)

E-mail address Randy.c@calderservice.com