



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District1033district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 07 2013

Date of Test 5-2-13 Operator Chevron Midcont API # 30-039-06648

Property Name Rincon Well No. 11 Location: Unit K Section 06 Township 26 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate 4 Casing 41 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
5 min	0	4	42	0	41	
10 min	0	4	42	0	41	
15 min	0	4	42	0	42	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X 8sec
Nothing	X PUFF
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

By Randy CalcoTE
Calder Service
(Position)

Witness _____

E-mail address Randy.C@calder-service.com

5-3-13