



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III/District.htm](http://emnr.d.state.nm.us/ocd/District%20III/District.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 01 2013

Date of Test 4-22-13 Operator Chewon midwest API #30-0 39 07045

Property Name Rincon Well No. 81 Location: Unit K Section 17 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 57 Intermediate X Casing 6 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		6		
10 min	0		6		
15 min	0		6		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X 12sec</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 5 INTERMEDIATE X

REMARKS: Bradenhead Blow down in 12sec

By Randy Caldoz
Caldoz
(Position)

Witness _____

E-mail address Randy.C@caldoservice.com

4-23-13