



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 24 2013

Date of Test 4/16/2013 Operator WPX Energy API #30-0 3926314

Property Name Rosa Unit Well No. 085A Location: Unit B Section 20 Township 31N Range 05W

Well Status(Shut-In or Producing) Initial PSI: Tubing 102 Intermediate NA Casing 105 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø	NA	105		
10 min	Ø	NA	105		
15 min	Ø	NA	105		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	N/A
Surges	
Down to Nothing	✓ in 1 sec
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE NA

REMARKS:

After 24 hour shut-in BH blew down to nothing in 1 second, left BH valve open after test.

By Stacey McLendon
Field Tech
(Position)

Witness _____

E-mail address Stacey.mclendon@wpxenergy.com