



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 18 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-11-13 Operator WPX Energy API #30-0 3927686

Property Name Rosa Unit Well No. 146A Location: Unit D Section 28 Township 31N Range 05W

Well Status (Shut-In or Producing) Initial PSI: Tubing 126 Intermediate N/A Casing 137 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0	N/A	137		
10 min	0	N/A	137		
15 min	0	N/A	137		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Bradenhead had 3 psi and blew down to
nothing. Left valve open

By Stanley Dean

Witness _____

Sr. Tech

(Position)

E-mail address stanley.dean@wpenergy.com