



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

DEC 29 2014

(submit 1 copy to above address)

Date of Test 12/29/2014 Operator Chervest API #30-0 45-10.310

Property Name Nance Well No. 1 Location: Unit J Section 22 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 200 Intermediate — Casing 265 Bradenhead 65

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	—	265		
10 min	0	—	265		
15 min	0	—	265		
20 min	0	—	265		
25 min	0	—	265		
30 min	0	—	265		

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 5 INTERMEDIATE _____

REMARKS:

Bradenhead down to slight blow at 6 min. blew for rest of 30 min.
Test Took gas samples

By My chervest
Lease operator
(Position)

Witness Paul Weber

E-mail address _____