

RECEIVED  
NOV 07 2014

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

*SUBMIT IN TRIPLICATE - Other instructions on page 2.*

|   |   |   |
|---|---|---|
| 1. Type of Well<br><br><input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other                            |   | 5. Lease Serial No.<br>NMSF 078360                                      |
| 2. Name of Operator<br>WPX Energy Production, LLC   |   | 6. If Indian, Allottee or Tribe Name                                    |
| 3a. Address<br>PO Box 640    Aztec, NM 87410  | 3b. Phone No. (include area code)<br>505-333-1822 | 7. If Unit of CA/Agreement, Name and/or No.<br>CA 132829                |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)<br>SHL: 253' FSL & 196' FWL, Sec 18, T23N, R6W<br>BHL: 290' FNL & 230' FEL SEC 19 23N 6W |   | 8. Well Name and No.<br>NE CHACO COM #256H                              |
|   |   | 9. API Well No.<br>30-039-31236   |
|   |   | 10. Field and Pool or Exploratory Area<br><b>Chaco Unit NE HZ (oil)</b> |
|   |   | 11. Country or Parish, State<br>Rio Arriba, NM                          |

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                |   |  |   |
|---|---|---|--|---|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off   |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity   |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                | <input checked="" type="checkbox"/> Other |
|   | <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       | <b>Amended COMPLETION</b>                 |
|   | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |   |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

**OIL CONS. DIV DIST. 3**

WPX Energy would like to amend the following info.

NOV 18 2014

Should read:

**9/30/14**-Perf Gallup 1<sup>st</sup> stage, 10385'-10571' + RSI TOOL @ 10634' (FINAL CASING SUNDRY REPORTED RSI @ 10631') with 18, 0.40" holes

Reported incorrectly:

**9/30/14**-Perf Gallup 1<sup>st</sup> stage, 10385'-11571' + RSI TOOL @ 10634' (FINAL CASING SUNDRY REPORTED RSI @ 10631') with 18, 0.40" holes

|   |  |                       |
|---|--|-----------------------|
| 14. I hereby certify that the foregoing is true and correct.<br>Name (Printed/Typed)<br>Larry Higgins |  | Title Regulatory Spec |
| Signature   |  | Date 11/6/14          |

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

|   |        |      |
|---|--------|------|
| Approved by   | Title  | Date |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. | Office |      |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NOV 13 2014

**NMOC D**

FARMINGTON FIELD OFFICE  
BY: *William Tambekou*

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OIL CONS. DIV DIST. 3

OCT 27 2014

OCT 30 2014

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

Oil Well     Gas Well     Other

**CONFIDENTIAL**

2. Name of Operator

WPX Energy Production, LLC

3a. Address

PO Box 640    Aztec, NM 87410

3b. Phone No. (include area code)

505-333-1822

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SHL: 253' FSL & 196' FWL, Sec 18, T23N, R6W  
BHL: 290' FNL & 230' FEL SEC 19 23N 6W

5. Lease Serial No.

NMSF 078360

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.  
CA 132829

8. Well Name and No.

NE CHACO COM #256H

9. API Well No.

30-039-31236

10. Field and Pool or Exploratory Area  
**Chaco Unit NE HZ (oil)**

11. Country or Parish, State  
Rio Arriba, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                |   |  |  |
|---|---|---|--|--|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off                        |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity                        |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                | <input checked="" type="checkbox"/> Other<br><b>COMPLETION</b> |
|   | <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |  |
|   | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |  |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

9/18/14- MIRU HWS #22

9/19/14- Run Tie Back String-No-Go, and 4 1/2" 11.6# N80 casing as follows; Seal Assembly with No-Go 5.85" OD 4.00" ID, 30 Jts 4 1/2" 11.6# N80 casing, 10.08' X 4 1/2" 11.6# N80 casing sub/ Marker Jt set @ 4754.39 - 4754.47', 126 Jts 4 1/2" 11.6# N80 casing, 14.66', 19.7' casing subs, 1 Jt 4 1/2" 11.6# N80 casing, 1 X 2.50' casing sub, and casing hanger. Total length of all Tubulars ran in well = 5857.54'. Had an up wt of 69K and down wt of 58K. Landed with 40K on liner top and leaving 13K on hanger. Total with KB difference is 5853.80'. Had a difference of 3.14' from liner hanger depth @ 5864.9' Antelope tested 4 1/2" casing to 1500 psi, held for 30minutes, and recorded on chart. Antelope tested 4 1/2" X 7' to 1500 psi, held for 30 minutes, and recorded on chart. Annulus tested good, and 4 1/2" had a psi loss of 100 psi in 30 minutes.

9/23/14-TIH with 3 7/8" junk mill, 3 7/8" string mill, bit sub, and 2 3/8" workstring to top of liner. RU power swivel, broke circulation with H2O. Cleaned out cement from 5862' to 6066'. RIH 2 more Jts to 6130'. Circulated clean. RD power swivel. TOH with Tbg and BHATIH with 4 1/2" Arrowset Packer and 2 3/8" Tbg, set @ 6050'RU Antelope to psi test down Tbg to 1500 psi, held for 30 mins, and recorded on chart. Had a psi loss of 150 psi in 30 mins. Psit down annulus to 1500 psi, held for 30 mins, and recorded on chart - tested good.

NOTE-9/24/14 Jamie Hall emailed Charlie Perrin with OCD:

Good Morning Charlie, I have attached the series of pressure tests for the Chaco 2306-18M #256H (API: 30-039-31236). After going in with a 4-1/2" packer set at 6050' below the liner top and 7" casing point, we were able to establish good integrity above the packer. Please let me know if you have any questions. We will be proceeding with opening the RSI in preparation for the frac.


14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Larry Higgins

Title Regulatory Spec

Signature



Date 10/23/14

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCDD

FARMINGTON FIELD OFFICE

BY: *William Tambekou*

Chaco 2306-18M #256H – page 2

9/24/14-CO to 10630'

9/25/14-RD HWS #22

9/30/14-Perf Gallup 1<sup>st</sup> stage, 10385'-11571' + RSI TOOL @ 10634' (FINAL CASING SUNDRY REPORTED RSI @ 10631') with 18, 0.40" holes

10/1/14 thru 10/5/14- Prepare for Frac

10/6/14-Frac Gallup 1<sup>st</sup> stage 10385'-10634'- with 201,000 # 20/40 PSA Sand

Set flo-thru frac plug @ 10310' MD. Perf 2<sup>nd</sup> 10004'-10265'- with 24 total, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 200,200#, 20/40 PSA Sand  
Set flo-thru frac plug @ 9960' MD. Perf 3<sup>rd</sup> stage 9748'-9900'- with 24, 0.40" holes.

10/7/14- Frac Gallup 3<sup>rd</sup> stage with 199,800#, 20/40 PSA Sand

Set flo-thru frac plug @ 9700' MD. Perf 4<sup>th</sup> stage 9492'-9649'- with 24, 0.40" holes. Frac Gallup 4<sup>th</sup> stage with 200,470#, 20/40 PSA Sand  
Set flo-thru frac plug @ 9460' MD. Perf 5<sup>th</sup> stage 9236'-9392'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 200,840#, 20/40 PSA Sand  
Set flo-thru frac plug @ 9200' MD. Perf 6<sup>th</sup> stage 8980'-9136'- with 24, 0.40" holes.

10/8/14- Frac Gallup 6<sup>th</sup> stage with 196,200#, 20/40 PSA Sand

Set flo-thru frac plug @ 8920' MD. Perf 7<sup>th</sup> stage 8742'-8881'- with 24, 0.40" holes. Frac Gallup 7<sup>th</sup> stage with 205,000#, 20/40 PSA Sand  
Set flo-thru frac plug @ 8690' MD. Perf 8<sup>th</sup> stage 8468'-8624'- with 24, 0.40" holes. Frac Gallup 8<sup>th</sup> stage with 201,700#, 20/40 PSA Sand  
Set flo-thru frac plug @ 8430' MD. Perf 9<sup>th</sup> stage 8212'-8368'- with 24, 0.40" holes. Frac Gallup 9<sup>th</sup> stage with 195,580#, 20/40 PSA Sand  
Set flo-thru frac plug @ 8160' MD. Perf 10<sup>th</sup> stage 7941'-8368'- with 24, 0.40" holes.

10/9/14-Frac Gallup 10<sup>th</sup> stage with 202,560#, 20/40 PSA Sand

Set flo-thru frac plug @ 7900' MD. Perf 11<sup>th</sup> stage 7580'-7842'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 203,700#, 20/40 PSA Sand  
Set flo-thru frac plug @ 7550' MD. Perf 12<sup>th</sup> stage 7294'-7480'- with 24, 0.40" holes. Frac Gallup 12<sup>th</sup> stage with 237,460# 20/40 PSA Sand

10/10/14-Set flo-thru frac plug @ 7230' MD. Perf 13<sup>th</sup> stage 6998'-7184'- with 24, 0.40" holes. Frac Gallup 13<sup>th</sup> stage with 233,982#, 20/40 PSA Sand

Set flo-thru frac plug @ 6970' MD. Perf 14<sup>th</sup> stage 6697'-6897'- with 24, 0.40" holes. Frac Gallup 14<sup>th</sup> stage with 244,000#, 20/40 PSA Sand  
Set flo-thru frac plug @ 6630' MD. Perf 15<sup>th</sup> stage 6396'-6597'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 234,580#, 20/40 PSA Sand  
Set flo-thru frac plug @ 6330' MD. Perf 16<sup>th</sup> stage 6095'-6296'- with 24, 0.40" holes.

10/11/14- Frac Gallup 16<sup>th</sup> stage with 272,600#, 20/40 PSA Sand

Set 4-1/2" CIPB @ 4990'

10/16/14- MIRU HWS #10

TEST BOP

10/17/14-DO CIBP @ 4990' DO flo thru Frac plug @ 6330', 6630', 6970', 7230', 7550', 7900', 8160' and 8430'

10/18/14- DO flo thru Frac plug @ 8690', 8920', 9200', 9460', 9700', 9960' and 10310'

Flow, test and C/O well 10633' MD

10/19/14-Land well at 5728' w/ 14.5' KB as follows 1/2 MS, 1 Jt of 2.375" J55 4.7lb 8rnd EUE tbg, 1.50" FN at 5697', 177 Jts of 2.375" J55 4.7lb 8rnd EUE tbg 178 jts total

10/21/14-First deliver Oil to sales

Choke Size= 54/64", Tbg Prsr= 480 psi, Csg Prsr= 1200 psi, Sep Prsr= 90 psi, Sep Temp= 100 degrees F, Flow Line Temp= 99 degrees F, Flow Rate= 2896 mcf/d, 24hr Fluid Avg= 35 bph, 24hr Wtr= 376 bbls, 24hr Wtr Avg= 16 bph, Total Wtr Accum= 3141 bbls, 24hr Oil= 453 bbls, 24hr Oil Avg= 19 bph, Total Oil Accum= 1569 bbls, 24hr Total Fluid= 829 bbls

**NOTE: 4-1/2" tie back string from surface to TOL @ 5865' will be removed at a later date when artificial lift is installed in this well.**