



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178
FAX: (505) 334-8170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/20/05 Operator FOUR STAR CHEVRON API #30-0 4508113
Property Name FLD COM BUNCE Well No. 1 Location: Unit 19 Section 29 Township 10 Range 10
Well Status (Shut-In or Producing) Tubing 190 Intermediate NA Casing 313 Bradenhead 31.2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
INITIAL TEST 1:45

		PRESSURES:		
TIME		BRADENHEAD	INTERMEDIATE	CASING
1:50	5 minutes	0		313
1:55	10 minutes	0		314
2:00	15 minutes	0		314
	20 minutes			
	25 minutes			
	30 minutes			


	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	1:30	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

2:05 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS: 1/4" VALVE



By MIKE DREYER
MAINTENANCE PLANNER
(Position)

Witness NONE - DARYL IS GONE
TOLD TO CONT TESTING

E-mail address MLDR@CHEVRON.COM