



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/20/05 Operator CHEVRON API #30-0 4523130  
Property Name BUNCE A FLD Well No. 1 Location: Unit 192 Section 19 Township 29 Range 10  
Well Status (Shut-In or Producing) Tubing NA Intermediate 214 Casing 214 Bradenhead 5.0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

INITIAL TEST 2:40

PRESSURES:

TIME	BRADENHEAD	INTERMEDIATE	CASING
2:45 5 minutes	0		224
2:50 10 minutes	0		224
2:55 15 minutes	0		224
20 minutes			
25 minutes			
30 minutes			

BRADENHEAD FLOWED INTERMEDIATE FLOWED


Steady Flow \_\_\_\_\_  
Surges \_\_\_\_\_  
Down to Nothing 20 SEC  
Nothing \_\_\_\_\_  
Gas 0  
Gas & Water \_\_\_\_\_  
Water \_\_\_\_\_

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

3:05 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS: 1/4" BLEEDER -



By MIKE DREYER  
MAINTENANCE PLANNER  
(Position)

Witness DARYL IS NO LONGER AT  
EMNRD TO CONTINUE TESTING

E-mail address MLDRE@CHEVRON.COM