

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837	
Facility Name: Carle 1	Facility Type: Gas Well	
Surface Owner BLM	Mineral Owner BLM (SF-078402-A)	API No. 30-045-09395

LOCATION OF RELEASE

Unit Letter C	Section 20	Township 30N	Range 11W	Feet from the 990'	North/South Line North	Feet from the 1650'	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

Latitude **36.80225** Longitude **-108.01701**

NATURE OF RELEASE

Type of Release Hydrocarbon & Produced Water	Volume of Release 57bbls Hydrocarbon & 13 bbls PW	Volume Recovered 5bbls Hydrocarbon & 1bbl PW
Source of Release Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1/15/15 at 3:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM (Shari Ketcham) & OCD (Cory Smith-	
By Whom? Lisa Hunter	Date and Hour 1/16/2015 at 2:40PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The MSO discovered a release from the production tank on the subject well from a hole on the inspection plate flange. 57bbls of hydrocarbon and 13bbls of produced water was released. The well was immediately shut-in and a SPEC truck called. 5bbls of hydrocarbon was recovered and 1bbl of produced water.

Describe Area Affected and Cleanup Action Taken.*



ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

RECEIVED

JAN 23 2015

NMOC

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 3/13/15	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	
Date: 1/20/2015 Phone: (505) 326-9837		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

#NCS 1507241529

①