

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

JAN 15 2015

Release Notification and Corrective Action

OPERATOR

NMOCD
DISTRICT III

☒ Initial Report ☒ Final Report

Name of Company: BP America	Contact: Jeff Peace
Address: 200 Energy Court, Farmington, NM 87401	Telephone No. (505) 326-9479
Facility Name: State Gas Com I I	Facility Type: Natural Gas Well

Surface Owner: State	Mineral Owner: State	API No. 3004508694
----------------------	----------------------	--------------------

LOCATION OF RELEASE

Unit Letter K	Section 2	Township 29N	Range 9W	Feet from the 1825'	North/South Line South	Feet from the 1,560	East/West Line West	County San Juan
------------------	--------------	-----------------	-------------	------------------------	---------------------------	------------------------	------------------------	--------------------

Latitude 36.75129 Longitude 107.75241

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 543 Mcf	Volume Recovered: None
Source of Release: water dump valve on compressor separator	Date and Hour of Occurrence: 1/10/15; 6:00 PM – 1/12/2015; 8:00 AM	Date and Hour of Discovery: 1/12/2015; 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith	
By Whom? Jeff Peace	Date and Hour: 1/13/2015; 3:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Field tech arrived on location after receiving report the compressor was not running. When he got to the well he noticed gas was blowing through the water dump from the compressor separator. The dump valve was stuck in the open position. The field tech shut the well in.

Describe Area Affected and Cleanup Action Taken.*

The released gas dissipated into the atmosphere. No cleanup action was possible. The dump valve will be repaired or replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jeff Peace	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: 3/23/15	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 13, 2015	Phone: (505) 326-9479	

* Attach Additional Sheets If Necessary

#NCS 150 82-34 750

①