



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

APR 23 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-22-15 Operator Dancy Wilcox API #30-0 39-05236
Property Name CP State Well No. 2 Location: Unit Section 36 Township 24 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 127 Intermediate ✓ Casing 126 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>126</u>			
10 min	<u>0</u>		<u>126</u>			
15 min	<u>0</u>		<u>126</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE ✓

REMARKS:

Earthen pit. Light blow when opened
to nothing at 5 minutes

By Curtis Davis
(Position)

Witness Monica Kuehling

E-mail address