



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

MAY 06 2015

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170  
[http://emrds.state.nm.us/ocd/District III3district.htm](http://emrds.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-15 Operator Coleman API #30-0 45-20186

Property Name Hodges Well No. 15 Location: Unit B Section 87 Township 8N Range 86W

Well Status (Shut-In or Producing) Initial PSI: Tubing 118 Intermediate X Casing 117 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>119</u>		
10 min	<u>0</u>		<u>123</u>		
15 min	<u>0</u>		<u>129</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Plunger Well

By Cody Hannah

Witness \_\_\_\_\_

Leuse Operator  
(Position)

E-mail address \_\_\_\_\_