



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 08 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/8/2015 Operator Burlington API # 30-045 - 23129

Property Name Jernigan Well No. 3A Location: Unit Section 24 Township 27 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 884 Intermediate NA Casing 103 Bradenhead 23

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0.4		103		
10 min	0.4		105		
15 min	0.4		106		
20 min	0.4		107		
25 min	0.5		108		
30 min	0.5		109		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 17 INTERMEDIATE NA

REMARKS:

BH plumbed to BBT, flowed water entire test. Requested water samples from BH and production and well bore schematic. BH through 1"

By Jay Martinez
(Position)

Witness Joseph D. Kelly

E-mail address