



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III3distr.htm](http://emnrd.state.nm.us/ocd/District%20III3distr.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 11-MAY-2015 Operator VTO API #30-0 45 33415  
Property Name FEE Well No. 3C Location: Unit \_\_\_ Section 3 Township 8 Range 11  
Well Status (Shut-In or Producing) (Producing) Initial PSI: Tubing 125 Intermediate N/A Casing 170 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min			170		
10 min			170		
15 min			170		
20 min				N/A	
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	N/A
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_ FRESH \_\_\_ SALTY \_\_\_ SULFUR \_\_\_ BLACK \_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By William T. B...  
Case Operator  
(Position)

Witness John Durham

E-mail address \_\_\_\_\_