



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 13 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-13-15 Operator McElvain Energy API # 30-045-24491  
Property Name Fairview GCA Well No. 1E Location: Unit E Section 17 Township 30 Range 13  
Well Status (Shut-In or Producing) Initial PSI: Tubing 138 Intermediate N/A Casing 182 Bradenhead 34

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		178		
10 min	0		178		
15 min	0		180		
20 min	0		180		
25 min	0		180		
30 min	0		180		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>1</u>	<u>sumes</u>
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

House tap - Med had blow to vapors/light  
blow at 30 seconds. vapors at 50 seconds.

sumes at 5 min. 10-15-20-25-30

By Alan Atwood

Witness Mamea Kuehling

(Position)

long puff when opened after  
5 min shut in.

E-mail address \_\_\_\_\_