NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 18-MAY 2015 Operator BP API #30-0 45-32921

Property Name BLANCO COM 2 Well No. 113 Location: Unit ___ Section 2 Township 30 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 127 Intermediate N/A Casing 247 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min			247		
10 min			247		
15 min			247		
20 min					
25 min					
30 min					

N/A

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT. THE BRADENHEAD WAS ON A VACUUM.

By [signature] Witness [signature]

Brandon Kennedy
(Position)

E-mail address _____

OIL CONS. DIV DIST. 3

MAY 18 2015