



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/21/2015 Operator COPC API #30-0 45-10078

Property Name Heaton Well No. 1 Location: Unit L Section 33 Township 31 Range 11

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 172 Intermediate - Casing 174 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	-	174		
10 min	0	-	174		
15 min	0	-	174		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

MAY 21 2015

REMARKS:

Nothing on bradenhead

By TD Eyer

Witness Paul Wicks

NSO
(Position)

E-mail address _____