



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-21-15 Operator W. J. J. J. J. API #30-0 45-24265
Property Name Stella Needsa Com Well No. 1E Location: Unit 36 Township 30 Range 14
Well Status (Shut-In or Producing) Initial PSI: Tubing 1050 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
MAY 21 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Med light blow to ~~test~~ vapors then dead
at 1 min. 30 seconds.
light blow when opened after a 5 min shut in
By Juan Acosta Witness Monica Kunkling
(Position)

E-mail address