



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 26 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-26-15 Operator Burlington Res API #30-0 45-09473  
Property Name Morris A Well No. 5 Location: Unit      Section 15 Township 30 Range 11  
Well Status(Shut-In or Producing) Initial PSI: Tubing 64 Intermediate 0 Casing 64 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	64	0	64
10 min	0	0	64	0	64
15 min	0	0	64	0	64
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH - light puff when opened.  
Int - light puff when opened.  
Well has 90 on BH.

By Don Thompson

Witness Monica Kuehling

(Position)

E-mail address