



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6170 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

OIL CONS. DIV DIST. 3

JUN 01 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-JUNE-2015 Operator BP API #30-0 45-24988

Property Name HEATON COMUS Well No. 9A Location: Unit 1 Section 32 Township 31 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 140 Intermediate N/A Casing 87 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			87		
10 min			87		
15 min			87		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT PRODUCED
DOWN TO NOTHING IN 5 SECONDS
REQUESTED A GAS ANALYSIS

By [Signature]

Witness [Signature]

(Position)

E-mail address _____