



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 21 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-14-15 Operator DS Simmons API #30-045-34119

Property Name Blanca Wash Well No. 06-1 Location: Unit K Section 06 Township 8N Range 24W

Well Status (Shut-In or Producing) Initial PSI: Tubing 113 Intermediate 1 Casing 113 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>114</u>		
10 min	<u>0</u>		<u>114</u>		
15 min	<u>0</u>		<u>113</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Oil well with pumping unit. Tied to CDP.

By Cody Hannah

Witness Paul Wulfe

Lease Operator
(Position)

E-mail address _____