



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3distric.htm>

OIL CONS. DIV DIST. 3

JUN 10 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test May 7, 2015 Operator Koch Exploration Company, LLC API #30-045-24214

Property Name Dryden Well No. 1 Location: Unit D Section 28 Township 28N Range 08W

Well Status(Shut-In or Producing) Initial PSI: Tubing 172 Intermediate 0 Casing 194 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>194</u>		
10 min	<u>0</u>	<u>0</u>	<u>194</u>		
15 min	<u>0</u>	<u>0</u>	<u>193</u>		
20 min				<u>0</u>	<u>193</u>
25 min				<u>0</u>	<u>193</u>
30 min				<u>0</u>	<u>193</u>

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>✓</u>	<u>✓</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

By Kenneth Cogh
Operations Technician
(Position)

Witness _____

E-mail address _____