



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT
OIL CONS. DIV DIST. 3

JUN 15 2015

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 15-JUNE-2015 Operator CROSS TIMBERS API #30-0 45-31342
Property Name PAN AM STATE Well No. 1B Location: Union Section 36 Township 32 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 77 Intermediate N/A Casing 90 Bradenhead 88

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min			90		
10 min			90		
15 min			90		
20 min			90		
25 min			80		
30 min			80		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT HAD A STRONG
FLOW FOR THE FIRST FEW SECONDS AND THEN HAD A
LIGHT FLOW FOR THE REMAINDER OF THE TEST. REQUESTED A LMS
ANALYSIS

By [Signature]

Witness John Dudson

(Position)

E-mail address _____

36.937744 49639
- 108.16153986