



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

OIL CONS. DIV DIST. 3

JUN 12 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-12-15 Operator MEG Dullong API #30-0 45-07234
Property Name Krause Well No. 18 Location: Unit A Section 29 Township 28 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 2 Intermediate N/A Casing 80 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		80		
10 min	0		80		
15 min	0		80		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	
Nothing		
Gas	/	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Puff when opened.

Nothing when opened after 5 min shut in

By David Hinson
Field Foreman
(Position)

Witness Monica Cullins

E-mail address _____