



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-1-14 Operator Devon Energy API #30-0 45-27341
Property Name Middle Mesa SWD Well No. 1 Location: Unit 32 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 1203 Intermediate 15 Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	15	22	0	23
10 min	0	15	22	0	23
15 min	0	15	23	0	23
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow		
Surges		DIST. 8
Down to Nothing	/	OIL CONS. DIV.
Nothing		
Gas	/	PCVD JUL 1 '14
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH Duff when opened.
Int Haul blow - cleared at 1 min 50 seconds.

By Phil Jones
LEASE OPERATOR TECH
(Position)

Witness Mona Kuehling

E-mail address _____