



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

JUL 13 2015

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 7-13-15 Operator Nuron Energy API # 30-0 45-27340

Property Name NEBU Pump Mesa Well # 1 Location: Unit N Sec 36 Twn 31 Rge 8

Land Type:

State ☒
Federal ☐
Private ☐
Indian ☐

Well Type:

Water Injection ☐
Salt Water Disposal ☒
Gas Injection ☐
Producing Oil/Gas ☐
Pressure observation ☐

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 1829
Int. Casing Pres. 0

Pressured annulus up to 400-500-1025 psi. for _____ mins. Test passed/failed

REMARKS:

Left to Brandon & Charlie to Pass or fail

By PLW
(Operator Representative)

Witness Monica Kuchling
(NMOCD)

LEKE OPERATOR
(Position)

Revised 02-11-02

60 0

5

OIL CONS. DIV DIST. 3
JUL 13 2015

10

50

Graphic Controls LLC

CHART NO. MC MP-3000-1H

METER

TAKEN OFF

CHART PUT ON

LOCATION

REMARKS

30.045v 27340

July 13 2015

DEBU Hampden Ave. #1

Hold at 1025

15

20

25

30

35

40

45

PRINTED IN U.S.A.

