



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

JUL 15 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 15-JUL-2015 Operator BLANK API #30-0 45-06000

Property Name HUEFANITO UNIT Well No 13 Location: Unit Section 1 Township 26 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 0 Casing 18 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
5 min		0	18		18
10 min		0	18		18
15 min		0	18		18
20 min		0	18		
25 min		0	18		
30 min		0	18		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>X</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	<u>X</u>
Gas <u> </u>	
Gas & Water <u> </u>	
Water <u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3

INTERMEDIATE 0

REMARKS: OPENED THE BRADENHEAD AND A GALLON AND A HALF
OF WATER FLOWED FROM IT OVER 30 MINUTES. OPENED THE
INTERMEDIATE AND NOTHING CAME OUT

By Rodriguez
ms
(Position)

Witness John Durham

E-mail address