



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

JUL 28 2015

(submit 1 copy to above address)

Date of Test 7-28-15 Operator Burlington API #30-0 45-20416

Property Name Hurford Well No. 196 Location: Unit 21 Section 24 Township 26 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 130 Intermediate 11A Casing 130 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		630		
10 min	0		630		
15 min	0		630		
20 min					
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	
Nothing		
Gas	/	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: BH dead at 15 seconds - nothing when
opened after 5 min shut in.
fix w/ seals by replacing all field pressure on B.

By [Signature]
(Position)

Witness [Signature]

E-mail address _____