

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

OIL CONS. DIV DIST. 3

JUL 3 1 2015

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

					-				
Date of Test	06/2	4/15	Operator —		Four Star Oil Ga		as #	API# 30	04532240
Property Nam	e	SHIOTANI 009			Locatio 	on: Unit D	Section 33 T	ownship 30	Range 12
(Well Name and Number)									
Pressure (Shut-in or Producing) Tubing 0 Intermediate 0 Casing 5 Bradenhead 0									
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
Ţ	Bradenhead				Interme	diate		Bradenhead	Intermediate
Time	BH Blowdown	Casing Monitor	Intermediate Monitor		Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	5					Steady Flow		
10 minutes	0	5	-				Surges		
15 minutes	0	5					Down to Nothing		
20 minutes							No Flow	X	
25 minutes	-						Gas		
30 minutes	-						Gas and Water		
5 minute SI	0						Water		
If bradenhead flowed water, check all of the descriptions that apply below:  Clear Fresh Salty Sulfur Black  REMARKS:									
Ву	Ŀ	ucinda Pa	ıdilla		Wi	tness			