

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Enervest Operating	Contact: Michael Dame HSE Associate
Address: 2700 Farmington Ave, Building K, Suite #1	Telephone No. 505-325-0318
Facility Name: Jicarilla A #007F	Facility Type: Gas Well

Surface Owner: Jicarilla Tribe	Mineral Owner: Enervest Operating	API No. 30-039-31171
--------------------------------	-----------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 17	Township 26N	Range 5W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
------------------	---------------	-----------------	-------------	---------------	------------------	---------------	----------------	----------------------

Latitude 36.49256 Longitude -107.38475

NATURE OF RELEASE

Type of Release. Produced Oil	Volume of Release. 20 BBLs	Volume Recovered. Unknown
Source of Release. Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 7/21/2015. 8:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The cause of the problem is human error by not gauging their tank properly on this particular well. The remedial action that is being taken is by removing all contaminated dirt and gravel to Envirotech Land Farm. Soil samples will be taken and analyzed at Envirotech Laboratory, which once we have passed NMOCD regulations. We will get clean dirt from the local area and fill the excavation site back in and contour the location back to standard.

Describe Area Affected and Cleanup Action Taken.*

The affected area is contained within the fire wall in front of 3 production tanks. The action of clean up that is taking place is cleaning up all the contaminated dirt and removing it from the location. For further clean up action Enervest Operating is following the direction from Hobson Sandoval (Jicarilla Tribal EPOC) on how the Jicarilla Tribe would like the rest of the spill site to be cleaned up. We will continue to clean all contaminated dirt until it is clean and passes NMOCD standards, all soil analysis will be from taken and analyzed by Envirotech Laboratory.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Dame	Approved by Environmental Specialist: 	
Title: HSE Associate	Approval Date: 8/3/15	Expiration Date:
E-mail Address: mdame@enervest.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/22/2015	Phone: 505-325-0318	

* Attach Additional Sheets If Necessary

#NCS 1521552884